




REPLACEMENT SHEET

1/4

Fig. 1

(A) Transition metal compound



M :Transition metal atom of Groups 3–11.


R¹ – R⁶ :H, hydrocarbon group, etc.

m :1 – 6

n :Number satisfying valence of M

X :Hal, hydrocarbon group, etc.

(B)






REPLACEMENT SHEET

2/4

Fig.2

(A) Transition metal compound



M : Transition metal atom of Groups 3–11

R¹ – R¹⁰ : Hal, hydrocarbon group, etc.

n : Number satisfying valence of M

X : Hal, etc.

Q : Hydrocarbon group of C₃ or more, etc.

(B)

